

Software History for ADPRO PRO Software – Configuration software for PRO, PRO E and PRO E-RF PIR

Update process and requirements:

It is always recommended to use the latest ADPRO PRO Software. The software including the necessary driver, manuals and quick installation guides can be downloaded from the Xtralis Security Solutions Support Site <http://www.xtralissecurity.com> or from the [HeiTel Partnerforum](#).

Please log in with your personal credentials and search for “**ADPRO PRO PIR**” software or file no. **29650**. For a PIR firmware update please refer to the “ADPRO PRO-E FlashLoader PIR Update” or file no. 29461.

ADPRO PRO 9.47 2018-07-26

- Bug fix of a flat trigger threshold for **PRO E-100, PRO E-100H, PRO E-400H**

ADPRO PRO 9.46 2017-09-26

- Default language set to English
- Various text improvements in blue help box
- Parameter scroll bar in scope view improved. Not all parameters have been listed in previous version
- **PRO E-100** showed the same configuration parameters than PRO E-100H. This has been corrected
- Firmware version will be displayed with two digits after the decimal point

The following features are prepared for Firmware 1.70 or above:

- Option added to switch on the LED in case of an alarm
- Sensitivity settings for **PRO E-100, PRO E-100H, PRO E-100RF and 400** series can be configured separately in Creep Zone, near, middle and far
- Current sensitivity settings of each zones in parameter menu added. Hint: Wireless unit **PRO E-100RF** indicates only the sensitivity of Creep Zone and Main Zone as a whole.
- Supply voltage display added
- Hardware type display added

ADPRO PRO 9.45 2017-03-10

- **PRO E-100RFn, PRO E-100RFe:**
 - Configuration (*.ini) files for PRO E-100RFn, PRO E-100RFe (8MHz version) added
 - Default value of compass settings is now set to “OFF”
- **PRO E-18WRFn, PRO E-18WRFe:**
 - translations improved of “Zone 1 OFF (Pulsecount ON)” and “Pulse counter ALM” (English and German)
 - Vandal Status will be displayed correctly
 - The “Delay Out” value has not been written to the detector

- System status display in scope view corrected

ADPRO PRO 9.43

2016-11-11

- Configuration (*.ini) files for **PRO E-45D** and **PRO E-45DH** added
- Software installation and update dialogue optimized
- Bug fixes:
 - The address range of the detector was limited to 127. This has been fixed and the address range is now 1 up to 255
 - The tooltip for the buttons “Read settings to detector” and “Send settings to detector” has been corrected
 - Factory output settings regarding IR alarms and pulse count for wired PIRs corrected
 - **PRO E-45D, PRO E-45DH**: Output configuration option „zone left“ and “zone right“ corrected
 - **PRO E-RF-Series**:
 - Vandal Protection could not be disabled. This is now corrected
 - Output settings of wireless PIRs could be set although not supported by the detector itself
 - Setting of Delay Out 1 in INI-Files corrected

ADPRO PRO 9.29

2015-10-26

- Configuration (*.ini) files for PRO E-400H added
- Adjustments of various configuration (*.ini) files
- Installer optimized